



RW Connection  
Landisville, PA 17538

Toll Free: 800-355-7974  
Local Phone: 717-898-5257  
Fax: 717-898-5282

www.rwconnection.com

Printed On: 2016-09-13:21:02:54

Page 1 Of 2

## Belt Inspection & Asset Report

<b>Completed Date:</b>	2016-08-02 15:49:50	<b>Entered By:</b>	mdappert
<b>Asset Description:</b>	240FT - 18" - 2-220 3/16 x 1/16 - VIKING PREMIUM	<b>Performed By:</b>	mdappert
<b>Asset #:</b>	105963582-01		
<b>Serial #:</b>	RWC3582-01	<b>Initial Location:</b>	Site/PHILADELPHIA PA
<b>Owner:</b>	BLACKWELL STONE	<b>Result:</b>	PASS
<b>City:</b>	Lancaster	<b>Instruction:</b>	N/A
<b>ChipID:</b>	IC05836700	<b>Comment:</b>	JOB WENT WELL. RETURNED TO SHOP AT 4:30 PM.

Attribute Description	Attribute Data	Field Description	Results	Comment
Belt Length	240'	Work Performed On:	2016-08-02	
Belt Width	18"	Work Performed By:	MIKE FRITZINGER	
Distributor Order Number	105963582	<b>Survey Questions</b>		
Equipment Name	2B STACKER	Is belt tracking properly?	YES	
Equipment Number	10596-BLC-01	Is there any evidence of edge damage?	NO	
Rubber Model	VIKING PREMIUM	Condition of idlers?	GOOD	
Belt Style	Standard Flat	Condition of head and tail pulleys and lagging?	HEAD PULLEY WORN	
Cover Compound	Grade 1	Are all idlers rolling?	YES	
# of Piles	2	Any roller damage?	NO	
Top Cover Thickness	3/16	Is there any damage to the conveyor frame?	NO	
Bottom Cover Thickness	1/16	Condition of splice?	GOOD	
Operating Tensile Strength	220	Any gauges/punctures in the belt?	YES	PHOTO ATTACHED
Textile Type	P,N	At loading zone, is it loading properly?	YES	
Splice Type	VULCANIZE			
Date of Installation	2015-04-17			
Notes				